


Line Tracer 04



- IR Sensor –

1. QTRX Sensor

About QTRX Sensor





About QTRX Sensor



View QTRX Sensor with IR Camera

About QTRX Sensor



2. IR Sensor Implementation

IR Sensor Initialization

```
// 0,2,4,6 IR Emitter
P5->SEL0 &= ~0x08;
P5->SEL1 &= ~0x08;      // GPIO
P5->DIR |= 0x08;        // OUTPUT
P5->OUT &= ~0x08;       // turn off 4 even IR LEDs

// 1,3,5,7 IR Emitter
P9->SEL0 &= ~0x04;
P9->SEL1 &= ~0x04;      // GPIO
P9->DIR |= 0x04;        // OUTPUT
P9->OUT &= ~0x04;       // turn off 4 odd IR LEDs

// 0~7 IR Sensor
P7->SEL0 &= ~0xFF;
P7->SEL1 &= ~0xFF;      // GPIO
P7->DIR &= ~0xFF;       // INPUT
```

IR Sensor Basic Usage

```
while(1) {  
    // Turn on IR LEDs  
    P5->OUT |= 0x08;  
    P9->OUT |= 0x04;  
  
    // Make P7.0-P7.7 as output  
    P7->DIR = 0xFF;  
    // Charges a capacitor  
    P7->OUT = 0xFF;  
    // Wait for fully charged  
    Clock_Delay1us(10);  
  
    // Make P7.0-P7.7 as input  
    P7->DIR = 0x00;
```

You should turn on the power!


```
    // Wait for a while  
    Clock_Delay1us(1000);  
  
    // Read P7.7-P7.0 Input  
    // white : 0, black : 1  
    sensor = P7->IN & 0x10;  
  
    if (sensor) {  
        P2->OUT |= 0x01;  
    } else {  
        P2->OUT &= ~0x07;  
    }  
  
    // Turn off IR LEDs  
    P5->OUT &= ~0x08;  
    P9->OUT &= ~0x04;  
  
    Clock_Delay1ms(10);  
}
```


IR Sensor Basic Usage

1) Turn on IR LED

- Turn on both even and odd emitters

```
// Turn on IR LEDs  
P5->OUT |= 0x08;  
P9->OUT |= 0x04;
```




IR Sensor Basic Usage

2) Charge Capacitors

- To charge, we should change P7->DIR to output and charge capacitors through P7->OUT = 0xFF
- We need to wait for fully charged

```
// Make P7.0-P7.7 as output  
P7->DIR = 0xFF;  
// Charges a capacitor  
P7->OUT = 0xFF;  
// Wait for fully charged  
Clock_Delay1us(10);
```



IR Sensor Basic Usage


3) Wait for a while after fully charged

- Capacitor is discharged slowly in a natural situation, But it is very slow
- When IR Sensor gets IR light, it discharges capacitor
- Using above property, we can distinguish between white and black surfaces


```
// Make P7.0-P7.7 as input
P7->DIR = 0x00;

// Wait for a while
Clock_Delay1us(1000);

// Read 5th sensor, not entire
sensor = P7->IN & 0x10;
```




No IR Light



With IR Light

IR Sensor Basic Usage

3) Wait for a while after fully charged



We have to read a sensor at this moment

IR Sensor Basic Usage

4) Read Sensor

- Make Port7 as input and read Port 7
- When we read 0, it means white
- When we read 1, it means black

```
// Read P7.7-P7.0 Input
// white : 0, black : 1
sensor = P7->IN & 0x10;

if (sensor) {
    P2->OUT |= 0x01;
} else {
    P2->OUT &= ~0x07;
}
```

IR Sensor Basic Usage

5) Turn Off LEDs

- To save energy, turn off IR LEDs and sleep for a while

```
// Turn off IR LEDs  
P5->OUT &= ~0x08;  
P9->OUT &= ~0x04;  
  
Clock_Delay1ms(10);
```

Tip for Setting Waiting Constant

```
while (1) {
    P5->OUT |= 0x08;
    P9->OUT |= 0x04;

    P7->DIR = 0xFF;
    P7->OUT = 0xFF;

    Clock_Delay1us(10);

    P7->DIR = 0x00;

    int i;
    for (i = 0; i < 10000; i++) {
        sensor = P7->IN & 0x10;
        if (!sensor) {
            printf("Timing Constant : %d\n", i);
            break;
        }
        Clock_Delay1us(1);
    }

    P5->OUT &= ~0x08;
    P9->OUT &= ~0x04;

    Clock_Delay1ms(10);
}
```

Timing Constant : 1713

Timing Constant : 1671

Timing Constant : 1689

...

Timing Constant : 311

Timing Constant : 305

Timing Constant : 310

...

Timing Constant : 790

Timing Constant : 785

Timing Constant : 791

No Reflection

White Surface

Black Surface

3. IR Sensor Activity

Line Follower - Sensor

Turn on LED when the line is located at the center of the robot



- PWM & DC Motor -

1. PWM


PWM Principle

We want to adjust the brightness of the LED

- 0V means 0% brightness
- 5V means 100% brightness
- 0.05V means 1% brightness?

-> No. Circuit would consider 0.05V as 0V

We need a way to convert a digital signal into an analog signal




PWM Principle

What is PWM

- Pulse Width Modulation**
- Digital to Analog Converter**


PWM Principle

50% duty cycle



It behaves like 2.5v

75% duty cycle



It behaves like 3.75v

PWM Example 1

```
while (1) {  
    turn_on_led(LED_RED);  
    Clock_Delay1ms(1);  
    turn_off_led();  
    Clock_Delay1ms(9);  
}
```

PWM Freq : 100Hz

Duty Cycle : 10%

```
while (1) {  
    turn_on_led(LED_RED);  
    Clock_Delay1ms(9);  
    turn_off_led();  
    Clock_Delay1ms(1);  
}
```

PWM Freq : 100Hz

Duty Cycle : 90%

PWM Example 2


```
int delay = 1;
while (1) {
    if (delay >= 10000) delay = 1;

    turn_on_led(LED_RED);
    Clock_Delay1us(10000-delay);
    turn_off_led();
    Clock_Delay1us(delay);

    delay += 100;
}
```

100% brightness -> 0% brightness for every second

Actual Voltage Change



How We See

2. Motor

Motor Port Map

LaunchPad	TI-RSLK chassis board	DRV8838	Description
P5.5	DIRR	PH	Right Motor Direction
P3.6	nSLPR	nSLEEP	Right Motor Sleep
P2.6	PWMR	EN	Right Motor PWM
P5.4	DIRL	PH	Left Motor Direction
P3.7	nSLPL	nSLEEP	Left Motor Sleep
P2.7	PWML	EN	Left Motor PWM

PH	EN	nSleep	Motor
0	0	1	Stop
1	0	1	Stop
0	1	1	Forward
1	1	1	Back

To go forward, set nSleep=1, PH=0, and activate EN

Motor Initialization

```
void motor_init(void) {
    P3->SEL0 &= ~0xC0;
    P3->SEL1 &= ~0xC0;           // 1) configure nSLPR & nSLPL as GPIO
    P3->DIR |= 0xC0;             // 2) make nSLPR & nSLPL as output
    P3->OUT &= ~0xC0;            // 3) output LOW

    P5->SEL0 &= ~0x30;
    P5->SEL1 &= ~0x30;           // 1) configure DIRR & DIRL as GPIO
    P5->DIR |= 0x30;             // 2) make DIRR & DIRL as output
    P5->OUT &= ~0x30;            // 3) output LOW

    P2->SEL0 &= ~0xC0;
    P2->SEL1 &= ~0xC0;           // 1) configure PWMR & PWML as GPIO
    P2->DIR |= 0xC0;             // 2) make PWMR & PWML as output
    P2->OUT &= ~0xC0;            // 3) output LOW
}
```

Motor Example

```
while (1) {  
    // Move forward  
    P5->OUT &= ~0x30;      // PH      = 0  
    P2->OUT |= 0xC0;        // EN      = 1  
    P3->OUT |= 0xC0;        // nSleep  = 1  
    Clock_Delay1ms(1000);  
  
    // Stop  
    P2->OUT &= ~0xC0;      // EN      = 0  
    Clock_Delay1ms(1000);  
}
```

You should turn on the power!


Motor Speed Control Example

```
// 0 < speed < 10000
int speed = 1000;
while (1) {
    // PWM High
    P5->OUT &= ~0x30;
    P2->OUT |= 0xC0;
    P3->OUT |= 0xC0;
    Clock_Delay1us(speed);

    // PWM Low
    P2->OUT &= ~0xC0;
    Clock_Delay1us(10000-speed);
}
```

3. Motor Activity

Stop at finish line



Move!

Don't Move!

4. Assignment

Submission guide (~10/18)

Turn on LED when the line is located at the center of the robot

